



Van Delden
ON-SITE
WASTEWATER SYSTEMS

San Antonio (210) 698-2000
Hill Country (830) 249-4000
www.vdwws.com

Aerobic System Service

Date: _____ Name: _____

Inspected	Operable	Inoperable	Repaired
Diffusers	✓		
Aerator Filter	✓		
Aerator	✓		
Irrigation Pump	✓		
Audio Alarm	✓		
Visual Alarm	✓		
Timer		✓	✓
Photocell	N/A		
Electrical Circuits	✓		
Chlorine Supply	✓*		
Spray Heads	✓		
Spray Field	✓		

Sludge in Aerobic Tank 10% Pump Tank 2"
Odor to System Yes / No PSI 9
Recommend Pumping Yes / No

Comments: Roots in aerobic tank + pump tank. removed some - call office for estimate to remove remaining roots. It is recommended to replace the swimming pool tabs with wastewater

Replaced timer. Thank You! tabs.

YOUR SERVICEMAN CALLED AT

Date: 3-22-16 Time: _____

Performed Routine Maintenance

MESSAGE:

Additional Messages on Back (If any).
Authorized Jet Distributor